



36 Draffin Road Hilton, New York 14468
Phone: 585-392-3434
Toll Free: 1-800-828-6351
Sales: sales@monroefluid.com
Technical: technical@monroefluid.com

Astro-Clean A

Overview

ASTRO-CLEAN A is a low foam alkaline cleaner designed to remove process oils, gummy deposits of oil, grease, swarf and normal shop soils from machine tools, floors, and other hard surfaces. It combines organic and mineral alkalinity builders, detergents, water conditioners and deodorizer for optimum performance.

Applications

The primary application of ASTRO-CLEAN A is for cleaning machine tool coolant sumps and surfaces. It may also be used for general cleaning with mop and bucket, auto scrubber or spray washer.

Mixing

Most Cleaning Applications	20:1 @ 70-110°F
Heavy Deposits of Soil and Sludge	10:1 @ 70° F. - 110° F.
Added Directly to Old Coolant	2-4% by volume

Directions for Use 1. Drain sump or system as completely as possible, removing any solids. 2. Add 1 gallon of ASTRO-CLEAN A for each 20 gallons of coolant capacity, fill sump with water to normal operating level and circulate for a period of at least 4 hours. 3. While cleaner is circulating, use a rag or brush to remove stubborn deposits on machine surfaces and in coolant troughs. Allow fluid to wash material into the sump. 4. Remove cleaner and all solids from the sump, then fill sump to normal operating level with water, add 1 gallon of ASTRO-CLEAN A for each 100 gallons of water and circulate for at least 1/2 hour. 5. Remove fluid from the sump and immediately recharge machine with the appropriate amount of metalworking fluid at the correct dilution; circulate for at least 1/2 hour to protect against corrosion. ALTERNATE SUMP CLEANING PROCEDURE (For minimal loss of productivity) 1. Add cleaner directly into present coolant at a rate of 2-4% by volume, then run production for 1-2 shifts. 2. Remove coolant/cleaner mixture and any chips, fill sump with enough water to circulate through pump and lines. 3. Remove rinse water and immediately recharge with fresh coolant at the correct dilution.

Typical Properties

Appearance-Concentrate	Clear Blue liquid
pH @ 20:1	10.8 ± 0.2
Specific Gravity @ 60°F	1.02 ± 0.03
Lbs/Gallon	8.5 ± 0.1
Flash point, PMCC	None

Material Safety Data Sheets are available for all products.
All reasonable care has been taken to ensure
that the above information is accurate as of the date of printing.